

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer Mahesh Kumar M
2. Name of the School St Francis Sales Senior School ^{Vizhinjam}
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

RCC Permanent building No. 2
 GF - 29.70 x 11.20 x 3.40
 FF - 29.70 x 11.20 x 3.40

RCC Permanent building No. 1
 GF - 62.50m x 10.40m x 3.40m
 FF - 62.50m x 10.40m x 3.40m
 SF - 62.50m x 10.40m x 3.40m
 Cellar - 46.60m x 12.30 x 3.40m
5. Period for which the certificate is issued 2023-24
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)Nil
7. Any major defects noticed which will render the building unsafe in any manner Nil
8. Whether maintenance works have been done properly Yes
9. Whether the structure is sound or not for conducting classes Yes the structure is sound under normal wind & weather conditions

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 29.5.2023 and found to be fit / unfit to conduct classes, for the period 2023-24 for the reasons stated above.

Place : Venganoor
Date : 29.5.2023



PRINCIPAL
ST. FRANCIS SALES SCHOOL
VIZHINJAM, TVPM-695523

MANAGER
ST. FRANCIS SALES SCHOOL
VIZHINJAM, TVPM

M
ASSISTANT ENGINEER
LSGD Section
Venganoor Grama Panchayath

[Signature]
ASSISTANT ENGINEER
LSGD Section
Venganoor Grama Panchayath